



January 2006 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1 New Year's Day	2 Check Air Permit. Keep paint & solvent usage records if required	3	4	5	6 STP <input type="checkbox"/>	7
8	9	10 DEQ Smoke School 10th- 12th at Lake Bistineau State Park	11 Hazardous Waste Rpt. Workshop - Alex.(318) 487-5439; Shreveport (318) 676-7811	12 Hazardous Waste Rpt. Workshop - W. Monroe (318) 397-6130	13 STP <input type="checkbox"/> Hazardous Waste Rpt. Workshop - Lafayette (337) 262-5962	14
15 **	16 Martin L. King, Jr. Day	17 Hazardous Waste Rpt. Workshop - Baton Rouge (225) 219-3248	18	19 UST Training - Baton Rouge (225) 219-3713 1-5 pm	20 STP <input type="checkbox"/>	21
22	23	24	25	26	27 STP <input type="checkbox"/>	28 ** Ann.;Semi-ann.; & Quart. Discharge Monitor Report Due
29	30	31	For <u>sanitary treatment plants (STP)</u> , check <u>weekly</u> : (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?		Reminder: DEQ Hazardous Waste Training Sessions occur in Jan.-Feb. Call your regional Technical Advisors for details (see directory on last page)	

*Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections. *

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



February 2006 Small Business Reporting Calendar



ALERT: Check Reports Due March 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1	2	3 STP <input type="checkbox"/>	4
5	6	7	8	9	10 STP <input type="checkbox"/>	11
12 Lincoln's Birthday	13	14 Valentine's Day	15 **	16 Environmental Reg. Compliance Conf.- Alexandria (318) 441-6251	17 STP <input type="checkbox"/>	18
19	20 Presidents' Day	21	22 UST Training-Lafayette (219-3713) 8-12N Washington's Birthday	23	24 STP <input type="checkbox"/>	Check Air Permit. Keep paint & solvent usage records if required
26	27	28 ** Mardi Gras				

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



March 2006

Small Business Reporting Calendar



ALERT: Check Reports due April 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1 Hazardous Waste Annual Report; Tier II Report Due Ash Wednesday	2	3 STP <input type="checkbox"/>	4
5	6	7	8	9	10 STP <input type="checkbox"/>	11
12	13	14 UST Training - Shreveport (225) 219-3713 8-12 Noon	15 **	16	17 STP <input type="checkbox"/> St. Patrick's Day	18
19	20	21	22	23	24 STP <input type="checkbox"/>	25
26	27	28 **	29	30 Annual Emission Inventory Report (EI) Due on 31st	31 STP <input type="checkbox"/>	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



April 2006 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?		QUESTIONS? 1-800-259-2890				1
		Check Air Permit. Keep paint and solvent usage records if required.				April Fool's Day
2 Daylight Savings Time Begins	3	4	5	6	7 STP <input type="checkbox"/>	8
<hr style="border: 1px solid red;"/> DEQ Smoke School in Baton Rouge, LA <hr style="border: 1px solid red;"/>						
9 Palm Sunday	10	11	12	13 Passover	14 STP <input type="checkbox"/> Good Friday	15 ** Federal Income Taxes due
16 Easter	17	18 UST Training - Baton Rouge (225) 219-3713 1-5 pm	19	20	21 STP <input type="checkbox"/>	22 Earth Day
23 <div style="border: 1px solid black; width: 100%; height: 100%; transform: rotate(45deg); position: relative; margin-top: 10px;"> 30 </div>	24	25	26 Administrative Professionals Day	27 Quarterly Discharge Monitoring Report Due on 28th	28 STP <input type="checkbox"/> **	29

*Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections. *

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



May 2006 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Keep paint & solvent usage records if required.	1 Ozone Season Begins (May through September)	2	3	4	5 STP <input type="checkbox"/>	6
7	8	9	10	11	12 STP <input type="checkbox"/>	13
14 Mother's Day	15 ** Louisiana state income taxes due	16	17 UST Training - Lake Charles (225) 219-3713 8-12 Noon	18	19 STP <input type="checkbox"/>	20 Armed Forces Day
21	22	23	24	25	26 STP <input type="checkbox"/>	27
28 **	29 Memorial Day	30	31	For <u>sanitary treatment plants (STP)</u>, check <u>weekly</u>: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?		

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



June 2006 Small Business Reporting Calendar



ALERT: Check Reports due July 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For <u>sanitary treatment plants (STP)</u> , check <u>weekly</u> : (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?		NOTE: annual PERC Report due <u>July 1st</u> (see attached form)	Check Air Permit. Keep paint and solvent usage records if required.	1	2 STP <input type="checkbox"/>	3
4	5	6	7	8	9 STP <input type="checkbox"/>	10
11	12	13	14 Flag Day	15 **	16 STP <input type="checkbox"/>	17
18 Father's Day	19	20	21	22 UST Training - Kenner (225) 219-3713 1-5 pm	23 STP <input type="checkbox"/>	24
25	26	27	28 **	29 UST Training - Kenner 1-5 pm (225) 219-3713	30 STP <input type="checkbox"/>	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



July 2006 Small Business Reporting Calendar



DEQ permit maintenance fee invoicing begins. Pay by due date to keep active.

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For <u>sanitary treatment plants (STP)</u> , check <u>weekly</u> : (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?			Check Air Permit. Paint & solvent usage records may be required.			1 TEDI; Form R(TRI); Minor Source Air Toxic Rpts; and <u>PERC Report Due</u>
2	3	4 Independence Day	5	6	7 STP <input type="checkbox"/>	8
9	10	11 <u>DEQ Smoke School at Lake Bistineau State Park, LA</u>	12	13	14 STP <input type="checkbox"/>	15 **
16	17	18 UST Training - West Monroe (225) 219-3713 8-12 Noon	19	20	21 STP <input type="checkbox"/>	22
23 30	24 31	25	26	27 Semi-annual & Quart. Discharge Monitoring Report Due 28th	28 STP <input type="checkbox"/> **	29

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



August 2006

Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
QUESTIONS? 1-800-259-2890	Check Air Permit. Keep paint & solvent usage records if required.	1 Ann. Rpt. for generators, processors, disposers of solid waste due	2	3	4 STP <input type="checkbox"/>	5
6	7	8	9	10	11 STP <input type="checkbox"/>	12
13	14	15 ** UST Training - Baton Rouge (225) 219-3713 1-5 pm	16	17	18 STP <input type="checkbox"/>	19
20	21	22	23	24	25 STP <input type="checkbox"/>	26
27	28 **	29	30	31	For <u>sanitary treatment plants (STP)</u>, check <u>weekly</u>: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



September 2006 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Keep paint & solvent usage records if required.	For <u>sanitary treatment plants (STP)</u> , check <u>weekly</u> : (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?				1 STP <input type="checkbox"/>	2
3	4 Labor Day	5	6	7	8 STP <input type="checkbox"/>	9
10	11	12	13	14 Asbestos & Lead Workshop, DEQ Conf. Center in Baton Rouge	15 STP <input type="checkbox"/> **	16
17	18	19	20 UST Training - Kenner (225) 219-3713 1-5 pm	21	22 STP <input type="checkbox"/>	23 Rosh Hashanah
24	25	26	27 UST Training - Kenner (225) 219-3713 1-5 pm	28 **	29 STP <input type="checkbox"/>	30 Stage II Certificates Expire Ozone Season Ends

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



October 2006

Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2 Yom Kippur	3	4	5	6 STP <input type="checkbox"/>	7
8	9 Columbus Day	10	11	12	13 STP <input type="checkbox"/>	14
15 **	16 National Boss' Day	17	18	19	20 STP <input type="checkbox"/>	21
22	23	24	25	26 UST Training - Lafayette (225) 219-3713 8-12 Noon	27 STP <input type="checkbox"/>	28 ** Quart. Discharge Monitoring Report Due
29 Daylight Savings Time Ends	30	31 Halloween	For <u>sanitary treatment plants (STP)</u> , check <u>weekly</u> : (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?; (3) foul odors from discharge, is discharge cloudy?			Check Air Permit. Keep paint & solvent usage records if required.

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



November 2006

Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Keep paint & solvent usage records if required.	QUESTIONS? 1- 800-259-2890		1 UST Worker Certification Renewal due All Saints' Day	2	3 STP <input type="checkbox"/>	4
5	6	7 Election Day	8	9	10 STP <input type="checkbox"/>	11 Veterans' Day
12	13	14 UST Training - Alexandria (225) 219-3713 8-12 Noon	15 **	16	17 STP <input type="checkbox"/>	18
19	20	21	22	23 Thanksgiving Day	24 STP <input type="checkbox"/>	25
26	27	28 **	29	30	For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge, is discharge cloudy?	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

****Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)****



December 2006 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge, is discharge cloudy?		Check Air Permit. Keep paint & solvent usage records if required.	QUESTIONS? 1-800-259-2890	***UST Worker Certification expires on 31st	1 STP <input type="checkbox"/>	2
3	4	5	6	7	8 STP <input type="checkbox"/>	9
10	11	12 UST Training - Lake Charles (225) 219-3713 1-5 pm	13	14	15 STP <input type="checkbox"/> **	16 Hanukkah
17	18	19	20	21	22 STP <input type="checkbox"/>	23
24 *** 31	25 Christmas Day	26	27	28 **	29 STP <input type="checkbox"/>	30

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)